



Date: Thursday, 14/02/2008 1:48:32 PM  
User: Linda Lacelle















# Process Sheet

<b>Customer</b> : CC-DAR01 Dart Aerospace Ltd.	<b>Drawing Name</b> : D2350
<b>Job Number</b> : 37457	
<b>Estimate Number</b> : 10804	
<b>P.O. Number</b> :	<b>Part Number</b> : D2350
<b>This Issue</b> : 14/02/2008 <b>S.O. No.</b> :	<b>Drawing Number</b> : RTN08-011
<b>Prsht Rev.</b> : NC	<b>Project Number</b> :
<b>First Issue</b> : / / <b>Type</b> : SMALL /MED FAB	<b>Drawing Revision</b> :
<b>Previous Run</b> : 00015	<b>Material</b> :
<b>Written By</b> : 	<b>Due Date</b> : 21/02/2008 <b>Qty:</b> 2 <b>Um:</b> Each
<b>Checked &amp; Approved By</b> : 	
<b>Comment</b> :	

## Additional Product

Job Number:



Seq. #:	Machine Or Operation:	Description :
1.0	QC5	INSPECT WORK TO CURRENT STEP
		
<b>Comment:</b> INSPECT WORK TO CURRENT STEP 		
2.0	D2350	Litter Tie-Down Assembly
		
<b>Comment:</b> Qty.: 1.0000 Each(s)/Unit Total : 2.0000 Each(s) Litter Tie-Down Assembly Qty 2 of 5 from RTN 08-011. Original B33777.		
3.0	HAND FINISHING1	HAND FINISHING RESOURCE #1
		
<b>Comment:</b> HAND FINISHING RESOURCE #1 - Dis-assemble Qty 2 D2350 tie downs. Identify the hardware and keep for re-assembly. - Sand with a 320 grit to remove the defects in the powder coat finish  - Touch up , very nice and carefully, the affected area with alodine as per QSI 005.		
4.0	QC5	INSPECT WORK TO CURRENT STEP
		
<b>Comment:</b> INSPECT WORK TO CURRENT STEP 		
5.0	HAND FINISHING1	HAND FINISHING RESOURCE #1
		
<b>Comment:</b> HAND FINISHING RESOURCE #1 Powder coat white per QSI 005. 		

Date: Thursday, 14/02/2008 1:48:32 PM  
User: Linda Lacelle

## Process Sheet

Customer: CC-DAR01 Dart Aerospace Ltd.

Drawing Name: D2350

Job Number: 37457

Part Number: D2350

Job Number:



Seq. #:

Machine Or Operation:

Description :

6.0

QC3

INSPECT POWDER COAT/CHEMICAL CONVERSION



Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION

5 08/12/19 (2)

7.0

HAND FINISHING1

HAND FINISHING RESOURCE #1



Comment: HAND FINISHING RESOURCE #1

-Re-assemble as per drawing, using the original hardware.

08/02/20 (2)

8.0

QC5

INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

08/02/20 (2)

9.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and stock with the new batch #.

Location:

57/85

08/02/20 (2)

10.0

QC21

FINAL INSPECTION/W/O RELEASE



Comment: FINAL INSPECTION/W/O RELEASE

08/02/25 (2)

Job Completion




08/02/25 (2)



DESIGN	DRAWN BY	DART AEROSPACE LTD VICTORIA INTERNATIONAL AIRPORT, CANADA	
B WILLIAMS	B WILLIAMS	DRAWING NO.	REV. B
CHECKED BW	APPROVED	D2350	SHEET 2 OF 2
DATE		TITLE	SCALE
95:02:20		LITTER TIE DOWN ASSEMBLY	

RELEASED  
960607



SHOP COPY  
RETURN TO  
ENGINEERING  
UNCONTROLLED COPY  
SUBJECT TO AMENDMENT  
WITHOUT NOTICE  
WORK ORDER  
NO. ~~4037457~~

4037457